## **A+ HOME INSPECTIONS**

d.b.a. A+ Services, LLC 193 Heathersett Drive Franklin, TN 37064 (615) 791-7433

May 24, 2007

Bert Ernie 123 Sesame Street Franklin, TN

As requested, A+ Home Inspections performed radon testing at the above referenced home. Testing was conducted using a continuous radon monitor (CRM). Since the radon results were

<u>above</u> the **EPA Protocol AVERAGE concentration of 4.0 PicoCuries/liter at 75.4**, the EPA recommends mitigation to be performed. You can find a certified radon mitigator on the EPA Radon Website at <a href="www.epa.gov/iaq/radon/">www.epa.gov/iaq/radon/</a> or at <a href="www.neha-nrpp.org/">www.neha-nrpp.org/</a>. There are also names listed in the yellow pages.

This test was conducted in accordance with the EPA guidelines. It is not a warranty or guarantee of the property, but simply reflects the results of the test. This report/analysis does not imply acceptance or responsibility for financial or health consequences. We recommend that ongoing tests be used as precautionary measures in any home or area where radon has been detected.

Thank you for choosing A+ Home Inspections in the detection of radon gas. We want to commend your recognition of radon as a potential health hazard. Your valuation of a clean air environment and your efforts to establish healthy climate conditions within a dwelling are of significant value.

Should you have any questions or need any additional information, please do not hesitate to call.

Sincerely,

A+ Home Inspections d.b.a. A+ Services, LLC Steve or Carmen Traylor National Environmental Health Association (NEHA), NHRP Certification ID number 102158RT

A+ Services, LLC

A+ Home Inspections

## Radon testing performed at: 123 Sesame Street

Franklin, TN

\_\_\_\_\_

Professional Radon Monitor

| Start Date | 5/22/2007   |
|------------|-------------|
| Start Time | 11:54:00 AM |
| End Date   | 5/24/2007   |
| End Time   | 7:30:00 PM  |
| Serial #   | 47006034    |

Location Finished Basement

## Data in pCi/l Time Interval 1 Hr

| 37.0 | 52.0 | 67.0 |
|------|------|------|
| 57.0 | 53.0 | 52.0 |
| 52.0 | 49.0 | 48.0 |
| 56.0 | 60.0 | 69.0 |
|      |      |      |
| 71.0 | 85.0 | 92.0 |
| 115  | 123  | 135  |
| 138  | 152  | 145  |
| 133  | 135  | 107  |
|      |      |      |
| 103  | 85.0 | 82.0 |
| 67.0 | 62.0 | 42.0 |
| 23.0 | 14.0 | 13.0 |
| 22.0 | 27.0 | 36.0 |
|      |      |      |
| 45.0 | 58.0 | 66.0 |
| 71.0 | 83.0 | 94.0 |
| 88.0 | 98.0 | 104  |
| 97.0 | 87.0 | 85.0 |
|      |      |      |
| 77.0 | 64.0 | 55.0 |
| 56.0 | 52.0 | 42.0 |
| 35.0 |      |      |
|      |      |      |

Overall Avg. .= 73.9 EPA Protocol Avg. = 75.4

Radon testing performed by:

A+ Home Inspections d.b.a. A+ Services, LLC 193 Heathersett Drive, Franklin, TN 37064 Carmen Traylor (615) 791-7433 National Proficiency Program Residential Measurement Provider

National Environmental Health Association (NEHA)

NEHA ID # 102158 RT